



Rider Name				
Contact				
Date				
Salesman/Technician				
(Updated 9-26-18)				

	Service Number	Description	Retail Pri	
	SRV-005	Shock Oil Change & Service	\$89.95	
	PC-02S	Shock Fluid	\$14.95	
	SRV-004	Fork Oil Change & Service	\$109.95	
	PC-01S	Fork Fluid	\$19.95	
П	Yes, change springs	if needed & charge me.   No, notify me if springs need	d to be changed.	
	Yes, change additional wear parts & charge me if needed.  No, notify me if additional wear parts are nee			
Re	e-Valve & Set Up: F	orks (please check the services you would like done.)		
	Service Number	Description	Retail Pri	
亍	SRV-002	Fork Re-Valve & Set Up	\$194.95	
ᆚ	FRI-036 (required)	Fork Fluid, Fork Piston (X2), Fork Piston Band (X2),	\$110.95	
		Mid Speed Valve Stop Plate (X2), Fork Spring Spacer (X2),		
		Fork MSV Slide Collars (X2)		
	Yes, change addition	al wear parts & charge me if needed. $\ \square$ No, notify me if ad	lditional wear parts are nee	
Re	e-Valve & Set Up: S	hock (please check the services you would like done.)		
	Service Number	Description	Retail Pri	
7	SRV-003	Shock Re-Valve & Set Up	\$164.95	
ㅗ	SRI-026 (required)	Shock Oil, Shock Shaft Nut (Showa)	\$14.95	
	Yes, change additional wear parts & charge me if needed.   No, notify me if additional wear parts are needed.			
Sp	orings (please check th	e services you would like done.)		
	Service Number	Service Job	Retail Pri	
	FS-	Fork Springs	\$129.95	
	SS-	Shock Spring	\$129.95	
	Yes, change springs	if needed & charge me. $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	d to be changed.	
Re	-Valve & Set Up: O	ptional Parts (please check the optional parts you would like pu	ut on.)	
his p	I want   I don't want product   this product   Ser	vice Number Description	Retail Pr	
	☐ ☐ BCk	Bladder Cap Kit Bladder Cap, Air Valve Cap, Air Valve For Bladder Cap	\$69.95	
	SPA	18450 Linkage Arm (136mm)	\$224.95	
		Shock Collars Upgrade Kit	\$58.95	



# SHOCK COLLAR UPGRADE HUSQVARNA/KAWASAKI/KTM/SUZUKI

### **NEW PRELOAD SHOCK COLLARS**

The problem with the OEM preload collars for the 2019 KX450, 2017-2019 RM-Z450 and the 2016-2019 KTM and Husqvarna models is its plastic composition. During use, the heat omitted from the shock body heats up the plastic as well. A combination of this, along with dirt working its way underneath, the plastic collar becomes deformed, which makes tuning and adjustment extremely difficult. Pro Circuit's solution is very simple. We now offer a CNC-machined 6061 aluminum preload collar with a zinc-plated steel lock ring for improved durability and much easier adjustments. Discard your problematic, plastic OEM preload collar and replace it with Pro Circuit's new preload collars to make future shock preload adjustments a breeze.

### **UPGRADE AVAILABLE FOR:**

- 2019 KX450
- 2017-2019 RM-Z450
- 2016-2019 Husqvarna TC 125
- 2017-2019 Husqvarna TC 250
- 2016-2019 Husqvarna FC 250/350/450
   2016-2019 KTM 250/350/450 XC-F
- 2016-2019 KTM 125 SX
- 2017-2019 KTM 250 SX
- 2016-2019 KTM 250/350/450 SX-F
- 2016 1/2 KTM 250/450 SX-F F.E.
- 2015 1/2 KTM 250/450 SX-F F.E.

## PRICING FOR UPGRADE:

\$58.95 (Retail)